





TIPO MOTORE	TIPO MACCHINA	TESTATA→	DIVENTA TESTATA↓	UTILIZZ.
Z482	T1600	16851-03040/2/7	17548-03049 + 1J002-83040 SENSOR W.T. + 16851-65512 CANDEL. X2 + 19077-53650 SEAL HEAT X2	
Z482C	KUBOTA R1-11	16855-03040 (fino a 489915) 16855-03042 (dal 489916)	17548-03049  1A308-03040  + 1J090-03310 GUARNIZIONE TESTA	
Z482BBS		16853-03040 (fino a 489915) 16853-03042 (dal 489916)	17548-03049  1A308-03040  + 1J090-03310 GUARNIZIONE TESTA	
Z600				
Z620KW	KH36	15732-03040		
D662BH	KX36(H)	16861-03042 16862-03040/2 16863-03040	16863-03049 + 3 seal 19077-53650	550,55 €
	KX36(H) >=550001	16861-03042 16862-03040/2 16863-03040	16863-03049 + 3 seal 19077-53650	550,55 €
D722BH1				
D722BH2	U10	17575-03042 16689-03049/2	1A304-03040 + 1J092-03310 G.TESTA	236,25 €
D722BH2	U10ALPHA	17575-03042 16689-03049/2	1A304-03040 + 1J092-03310 G.TESTA	236,25 €

TIPO MOTORE	TIPO MACCHINA	TESTATA→	DIVENTA TESTATA↓	UTILIZZ.
D722BH4	U10-3 ≤5Z9999	17575-03042 16689-03049/2	1A304-03040 + 1J092-03310 G.TESTA	236,25 €
D722BH4	U10-3 ≥6A0001	1E129-03040	1E388-03040 + 1J092-03310 G. Testa (Y. 750)	236,25 €
D722EBH	K008 ≥=20001	17575-03042 16689-03049/2	1A304-03040 + 1J092-03310 G.TESTA	236,25 €
D722EBH3	K008-3	17575-03042 16689-03049/2	1A304-03040 + 1J092-03310 G.TESTA	236,25 €
D722E2BH3	K008-3 ≤7TZ999	1E129-03040	1E388-03040 + 1J092-03310 G. Testa (Y. 750)	358,59 €
D722E3BH3	K008-3 ≥7U0001	1J002-03040	1J002-03040	738,28 €
D750		15371-03040	15371-03040	600,00 €
D782BH	KX36-3 ≥=550001	1G008-03040/6	1A303-03040 + 1J092-03310 G.TESTA	241,92 €
	KX41-2ALPHA	1E051-03040	1E051-03046	166,64 €
	U15(EU) ≤2Y8991	1E051-03040	1E051-03046	166,64 €
	U15(EU) ≥3A0001	1G008-03040/6	1A303-03040 + 1J092-03310 G.TESTA	241,92 €
	U15-3	1G008-03040/6	1A303-03040 + 1J092-03310 G.TESTA	241,92 €
D782-ET02? (Komatsu 3D67E)	KOMATSU PC16R-3HS	1G969-03040	1G969-03040 (contiene testata 1J093-03040 + g. testa 1J092-03310)	334,08 €

TIPO MOTORE	TIPO MACCHINA	TESTATA→	DIVENTA TESTATA↓	UTILIZZ.
D850		19267-03040		648,70 €
D902-BH-1	KX41-3SV >=550001	1G962-03042		646,95 €
	U17-3 ALPHA	1G962-03045		
D905E2BEUXL1	SCHAEFF	1G032-03040	1G032-03043	505,73 €
D950B	DE MARCO M. 01.2015	15532-03040	15532-03040	649,69 €
D950BH1	KH50; KH50H	15531-03040	15531-03040	791,02 €
D950BH1	KH41	15531-03040	15531-03040	791,02 €
D950BH2	KH51H	15531-03040	15531-03040	791,02 €
D950BH2	KH61	15531-03040	15531-03040	791,02 €
D1005	A175	16231-03040	16027-03044	614,95 €
D1005D	BOBCAT 463		16027-03044	614,95 €
D1105BH	KX41H	16032-03040 16261-03040	16032-03045 + guarn. 1E038-03310 + ?	614,95 €
D1105BH	KX41 >=550001	16261-03040	16032-03045 + 3 candlette 16851-65512 + 3 tenute 19077-53650 + guarniz. 1E038-03310	614,95 €
D1105BH5	U20; U20E; EX20U <1J0001	16032-03042	16032-03045 + guarn. 1E038-03310	614,95 €
D1105BH6	KX61-2	16032-03040/2	16032-03045 + guarn. 1E038-03310	614,95 €

TIPO MOTORE	TIPO MACCHINA	TESTATA→	DIVENTA TESTATA↓	UTILIZZ.
D1105BH7	KX41-2	16032-03040/2	16032-03045 + guarn. 1E038-03310	614,95 €
D1105BH7	KX41-2SV	16032-03042	16032-03045 + guarn. 1E038-03310	614,95 €
D1105BH7	KX36-2	16032-03042	16032-03045 + guarn. 1E038-03310	614,95 €
	KX36-2 ALPHA	16032-03042	16032-03045 + guarn. 1E038-03310	614,95 €
	KX41	16261-03040	16032-03045 + 3 candele 16851-65512 + 3 tenute 19077-53650 + guarniz. 1E038-03310	614,95 €
D1105BH9	KX61-2 ALPHA	16032-03042	16032-03045 + guarn. 1E038-03310	614,95 €
D1105BHG	KX61 (H)	16032-03040/2 16261-03040	16032-03045 + guarnizione	614,95 €
	KX61(H) 500001~550000	16261-03040	16032-03045 + 3 candele 16851-65512 + 3 tenute 19077-53650 + guarniz. 1E038-03310	614,95 €
D1105BHG	KX021-KX024	16261-03040	16032-03045 + 3 candele 16851-65512 + 3 tenute 19077-53650 + guarniz. 1E038-03310	614,95 €

TIPO MOTORE	TIPO MACCHINA	TESTATA→	DIVENTA TESTATA↓	UTILIZZ.
D1105BHG1	K022 - K025	16261-03040	16032-03045 + 3 candele 16851-65512 + 3 tenute 19077-53650 + guarniz. 1E038-03310	614,95 €
D1105BHGSR	AR20	16261-03040	16032-03045 + 3 candele 16851-65512 + 3 tenute 19077-53650 + guarniz. 1E038-03310	614,95 €
D1105 ????		1G053-03040		309,09 €
D1105EKBH5	U20; U20E; EX20U >=1J0001	1G065-03040	1G065-03044	337,54 €
	U20-3 ALPHA	1G065-03040/2/3/4	1G065-03044	337,54 €
D1105EBH10	U20-3	1G065-03040	1G065-03044	337,54 €
D1105EBH11	U25-3	1G065-03040	1G065-03044	337,54 €
	U25-3 ALPHA	1G065-03040/2/3/4	1G065-03044	337,54 €
D1105-E2-BH-SR2	RX205	1G065-03040	1G065-03044	337,54 €
D1105T-EU1	tratt. GIANNI FERRARI		1G643-03044	
D1402	KH30SR	15521-03040	15521-03043	761,48 €
D1402BH4	KH91 H	15521-03043/4	15521-03043	761,48 €
	KH70 H	15521-03044	15521-03043	761,48 €
D1403E2B/EUX3	SCHAEFF	1G971-03040	1G971-03040	749,95 €
D1503BHHC1		16424-03040	16424-03047	764,72 €
D1503MBH1/EKBH1	U30-3	1A051-03044	1A013-03044	783,36 €

TIPO MOTORE	TIPO MACCHINA	TESTATA→	DIVENTA TESTATA↓	UTILIZZ.
D1503MBH2/EKBH2	K030-3; K035-3	1A013-03044	1A013-03044	783,36 €
D1503MEBH1EC	KX91-3	1A051-03040	1A013-03044	783,36 €
D1503MEBH2EC	KX101-3	1A051-03040	1A013-03044	783,36 €
D1503MEBH2EC	U35-3	1A051-03040	1A013-03044	783,36 €
	KX91-3 ALPHA >=80001	1A051-03044	1A013-03044	783,36 €
	KX91-3 ALPHA >=70001	1A051-03044	1A013-03044	783,36 €
	KX101-3 ALPHA >=80001	1A051-03044	1A013-03044	783,36 €
	KX101-3 ALPHA >=70001	1A051-03044	1A013-03044	783,36 €
	U30-3 ALPHA-2	1A051-03044	1A013-03044	783,36 €
	U35-3 ALPHA	1A051-03044	1A013-03044	783,36 €
	U35-3 ALPHA-2KBM	1A051-03044	1A013-03044	783,36 €
D1503KA		1A051-03044	1A013-03044	783,36 €
V1305		16052-03044		447,75 €
V1505BH	KX71	16062-03040 16282-03040	16062-03045 + ?	868,61 €
V1505BH	KX026 ; KX027	16282-03040	16062-03045 + 4 candlette 16851-65512 + guarn. 16292-03310 + 4 seal 19077-53650	868,61 €
V1505BH1	K028	16062-03045	16062-03045	868,61 €

TIPO MOTORE	TIPO MACCHINA	TESTATA→	DIVENTA TESTATA↓	UTILIZZ.
V1505BH2	K030	16282-03040	16062-03045 + 4 candele 16851-65512 + guarn. 16292-03310 + 4 seal 19077-53650	868,61 €
V1505BH3	K035	16282-03040	16062-03045 + 4 candele 16851-65512 + guarn. 16292-03310 + 4 seal 19077-53650	868,61 €
V1505BH5	KX91-2	16062-03040/2	16062-03045	868,61 €
V1505BH6	U30; U35; U35(EU)	16062-03042	16062-03045	868,61 €
V1505BH8	KX71-2	16062-03040/2	16062-03045	868,61 €
V1505BH9	KX71-2 ALPHA	16062-03042	16062-03045	868,61 €
V1505BHG	KX030	16282-03040	16062-03045 + 4 candele 16851-65512 + guarn. 16292-03310 + 4 seal 19077-53650	868,61 €
V1505BHSR	AR30	16062-03042	16062-03045	868,61 €
V1505BHHC1	EX30-2	16062-03042	16062-03045	868,61 €
V1505BHHC2	EX35-2	16062-03042	16062-03045	868,61 €
V1505BHHC3	EX40UR-2	16062-03042	16062-03045	868,61 €
V1505BHHC4	EX30UR-3	16062-03042	16062-03045	868,61 €
	KX71(H) 50001~55000	16282-03040	16062-03045 + 4 candele 16851-65512 + guarn. 16292-03310 + 4 seal 19077-53650	868,61 €

TIPO MOTORE	TIPO MACCHINA	TESTATA→	DIVENTA TESTATA↓	UTILIZZ.
	KX71(H) >=550001	16282-03040	16062-03045 + 4 candlette 16851-65512 + guarn. 16292-03310 + 4 seal 19077-53650	868,61 €
V1505	KX71-3 KBM	1G092-03040	1G092-03044	493,20 €
V1505	KX61-3 KBN	1G092-03040	1G092-03044	493,20 €
V1505	s/n 1FA6013 montato su GIANNI FERRARI		1G092-03044	493,20 €
V1505TE2		16394-03040 su questo motore diventa	1G092-03044	493,20 €
V1505TE3		16394-03040 su questo motore diventa	1G679-03040	749,95 €
V1505TEB		16065-03040		795,23 €
V1702		15422-03044	15422-03040	899,72 €
D1703-(6)	GL33	16487-03040-7	16487-03040	819,07 €
D1703ME2BSHF1	SCHAEFF	1A033-03043	1A033-03043	765,00 €
D1803	KX101.3 alpha3	1G711-03040	1G711-03040	759,38 €
V1902BH4	KH-51SR ; KH52SR	19893-03040	15476-03043	896,48 €
V1902BH5	KX101K TA	15476-03040/3	15476-03043	896,48 €
V1902BH5	KX101/S >=55001	15476-03043	15476-03043	896,48 €
V1902BH5	KX033	15476-03043	15476-03043	896,48 €

TIPO MOTORE	TIPO MACCHINA	TESTATA→	DIVENTA TESTATA↓	UTILIZZ.
V1902BH5	KX101	15476-03043	15476-03043	896,48 €
V1902BH6	KX151	15476-03043/0	15476-03043	896,48 €
V1902BH6	KX-040	19893-03040	15476-03043	896,48 €
V1902BH6	KX045	19893-03040	15476-03043	896,48 €
	KX101 50001~55001	15476-03043	15476-03043	896,48 €
	KX151 >=50001	15476-03043	15476-03043	896,48 €
V1903	RAMMAX RW3000		16454-03040	870,75 €
V2003-TEU4	BOBCAT 341	1E013-03043	1E013-03043	1.022,98 €
V2003-M-T-E2B		1G624-03042	1G624-03042	488,45 €
V2003-T-E2B-AUSA-1		1E013-03043 1E013-03044 1E013-03045	1E013-03043/ 1E013-03044/ 1E013-03045	1.022,98 €
V2003-T-B-SSSU-4		1E013-03043	1E013-03043	1.022,98 €
V2203BH1	KX121-2	16429-03040	19077-03048/50	936,56 €
V2203BH2	KX161-2	16429-03040	19077-03048/50	936,56 €
V2203BH1	K038; CASE CK38	19077-03048	19077-03048/50	936,56 €
V2203BH2	K045	19077-03048	19077-03048/50	936,56 €
V2203BH2	K040	19077-03048	19077-03048/50	936,56 €
V2203BH6	U45	19077-03048	19077-03048/50	936,56 €
V2203BH6	U45(EU)	16429-03040	19077-03048/50	936,56 €
	KX161-3 ALPHA >=70001	1G780-03043	1G780-03043	772,03 €

TIPO MOTORE	TIPO MACCHINA	TESTATA→	DIVENTA TESTATA↓	UTILIZZ.
	KX121-3 ALPHA >=70001	1G780-03043	1G780-03043	772,03 €
V2203MEBH2	KX161-3	1A081-03042	1G780-03043 + 1 candeletta 15841-96020	772,03 €
V2203MEBH2	KX121-3	1A081-03042	1G780-03043 + 1 candeletta 15841-96020	772,03 €
V2203MEBH2	U45-3	1A081-03042	1G780-03043 + 1 candeletta 15841-96020	772,03 €
V2203E2BEUX3V		1G780-03042	1G780-03043	772,03 €
	U45-3 ALPHA	1G780-03043	1G780-03043	772,03 €
	U50-3 ALPHA	1G780-03043	1G780-03043	772,03 €
V2403-M-E2B-EU-Z4		1G851-03043	1G851-03043	772,03 €
V2403-M-E3B		1G896-03040		
V3300T-E2B		1C010-03023 1C040-03020	1C040-03027	1.191,80 €
V3307DI-T	KX080-3 ALPHA	1G777-03020	1G777-03022 + 1G772-13460 ARM VALVE BURI x8	
V3600 (forse anche V3600T)		1J530-03020	1J530-03024	843,75 €
V3800DI	KX080-3	1C020-03022/5/6/7		1.381,64 €